PRODUCT INFORMATION



SYNTEKO NATURAL



1608

Synteko NATURAL is an alkyd based solvent-free, faintly smelling oil with excellent properties. The oil is formulated for treatment of wood floors but also cork floors, wooden stairs, windowsills, benches etc.

AREA OF USE: especially recommended in areas where a high wear resistance is needed

PRODUCT PROPERTIES:

- o no solvent
- practically odour-less
- excellent coverage
- short drying time
- easy to use
- non-yellowing
- excellent resistance to wear
- re-coatable with waterbased top finishes
- can be tinted with Synteko TINTING PASTE

COVERAGE:

15 – 60 m²/l, depending on tools and wood species

TOOLS:

- Rubber spatula, 300-500 mm width
- Red pad
- Non-flocculent cotton cloth or trowel for polishing
- Clean tools with white spirit.
- Place used pads, cloths, spillages and waste in a sealed, water filled metal container immediately after use

TECHNICAL DATA:

BASE MATERIAL Alkyd ester

SOLVENTS No solvent

SOLIDS CONTENT Approx. 99%

VISCOSITY 320 cP ICI at 23 °C

DENSITY Approx. 955 kg/m³ (8,64 lbs./gal US)

(10,37 lb/gal UK)

FIRE HAZARDS Not flammable

TIME FOR
APPLICATION

It is recommended to wait about 3 hours after the last application before the final

buffing is made

DRYING TIME Approx. 16 hours at 23°C (73°F)/50% RH

STORAGE Store frost-free. Must be stored between +10°C (+50°F) and +30°C (+86°F)

SELF LIFE 24 months in unopened container

from production date (s. package)

PACKAGE SIZE 1L, 5L

DURING THE USE:

- The oil should have room temperature.
- Floor temperature must be between 15 and 25°C (60 to 77°F)
- The moisture content of the wood should be between 5% and 12%.
- Shake the can carefully before and during use.
- Do not apply areas larger than 20 m² at a time (10 m² at a time in good drying conditions).

BEFORE USING THE FLOOR

- The floor can be used 1-2 days after the last polishing
- Do not wet a floor treated with Synteko floor oils during the first week
- Wait for 3 days before laying rugs or carpets
- Do not use vapour-proof, non-skid underlays or other coverings
- Attach felt pads to the legs of chairs and tables in order to avoid scratching the finish.
- Vacuum or dry-mop floors regularly

ATTENTION!

- Do not allow unabsorbed oil to dry! Dried unabsorbed oil produces glossy spots on the surface.
- Too much oil will result in a longer drying time and longer time for over-coating.
- On wood with low absorption, leave some areas untreated during the first application. These areas will be filled during the redistribution procedure.
- The oxygen curing process will be extremely slow if the temperature is below 18 °C.
- Floor heating system must be turned on during application and polishing.
- Be sure to start regular maintenance before the surface is worn through to bare wood.
- NB! Place all organic materials like cloth in a metal container filled with water for at least 16 hours to avoid self-combustion. Dispose of them according to regulations.

SYNTEKO NATURAL DIRECTIONS FOR USE



OILING OF UNFINISHED FLOORS OR FLOORS WHERE OLD FINISH MUST BE REMOVED

1. PREPARATION

- Machine sand the surface to remove old treatments and impurities in the wood. The first sanding is made with a coarse sandpaper and high roller pressure.
- Make the floor surface as even as possible. If the floor is uneven in spots, sand locally to even out these areas.
- The final sanding is made with 100-120 grit sandpaper or screen, and with the lowest possible roller pressure.
 If roller pressure is too high, the soft springwood may be compressed. When moisture from the finish affects such softwood, it will raise the grain of the floor by swelling back to its original volume.
- Vacuum and tack the floor before applying the finish.
 Do not forget to remove dust on skirtings, windowsills, radiators, etc.

2. TINTING

- The mixing of NATURAL oil with TINTING PASTE 1675 is easily done by adding the tinting paste to the oil and shaking the container thoroughly (see separate product information).
- Always use full tubes of tinting paste.
- Be sure to completely empty the tube into the oil in order to avoid colour differences
- Tinted oil has all same properties as neutral oil.
- TINTING PASTE is available in 7 colours:



Ebenholz



Mahogany



Olive



Rose Wood



Steel Blue



Teak



White Wood

3. PREPARATION FOR OILING

- Before starting work, protect adjacent areas against splashing and spilling.
- The number of coats necessary depends on how much oil the floor will absorb.
- The best result is obtained with several thinner coats.
 Softwoods and beech absorb more; hard and exotic (oily) woods absorb less oil. The wood should be well fed, but not overfed.
- Plan your work well, large areas should be divided into smaller areas of 15 - 20 m² (161 - 215 ft²) or areas which are possible to handle in 20 minutes.
- In hot, dry weather the areas should be further reduced.
- Shake the can carefully before and during the use.

4. APPLICATION

- Apply Synteko NATURAL with an applicator with rubber blade (squeegee) or pour directly on floor and distribute with red pad.
- Use a small brush or a small applicator in areas where it is difficult to reach with the normal applicator. Too much oil in puddles will splash around.
- Use 150 r.p.m. or similar adjustment of the buffer.
 Redistribute the oil with a red pad it is necessary to start within 20 minutes in normal temperatures.
- Add more oil if necessary.
- Repeat the process as long as the wood is absorbing the oil.
- When the wood is saturated, rub the whole surface with a red pad using a 150 r.p.m. buffer.
- Remove all excess oil with a non-flocculent cotton cloth and a red pad.
- Change cloth or pad when it is filled up.

5. POLISHING

- After 3-4 hours the floor must be buffed using a red pad.
- Final polishing is done with a dry non-flocculent cotton cloth wrapped around the pad and 150-300 r.p.m. adjustment of the buffer.
- Do not allow unabsorbed oil to dry! Dried unabsorbed oil gives glossy spots on the surface.
- Re-polish secondary bleeding of oil with red pad before exposure to traffic 1 to 2 days after final polishing.

6. RE-COATING WITH WATERBASED FINISHES

- Re-coating of oiled floor gives us the opportunity to colour of finished floor, to enhance colouring of exotic woods and to reduce discolouring of waterborne finishes.
- This final coating gives the floor special protection and relieves maintenance.
- Oiled floor can be re-coated with all Synteko wateborne top finishes after 16 hours in normal conditions (read separate Product Information)
- Before finishing the surface must be light buffed with a dry non-flocculent cotton cloth wrapped around the pad and 150-300 r.p.m. adjustment of the buffer to take care of any bleeding oil.

SYNTEKO FLOOR OILS CARE AND MAINTENANCE



Surfaces treated with Synteko floor oils are easy to keep clean. Regular maintenance will restore your floor's lustre and keep it looking beautiful for very long time.

Vacuum cleaning and, if necessary, mopping with a **Synteko SOAP 1617** solution and a well wrung cloth is normally sufficient. Marks from rubber heels, shoe polish, lipstick, ink, etc. should be removed immediately with **Synteko REMOVER 1692** or with mineral spirits. Avoid scrubbing with coarse brush or strong detergents.

For periodic maintenance of floors treated with Synteko oils use **Synteko RE-COVER 1620.** How often you use it will depend on the amount of traffic and how often the floor is cleaned:

- normally every other year for residential areas
- approx. 2–4 times per year for commercial areas.

Be sure to begin regular maintenance before you wear through to the bare wood. You can also use RE-COVER for local repairing.

HOW DO I USE SOAP 1617?

- 1. When necessary, for regular cleaning, but no sooner than one week after oil treatment.
- Floors may be washed with a 1:20 dilution of Synteko SOAP in lukewarm water, using a well wrung cloth.

HOW DO I USE REMOVER 1692?

- 1. Vacuum or mop the floor to remove any dirt.
- 2. Prepare Synteko REMOVER as follows:
 - For normal cleaning, ½ 1 part Synteko REMOVER to 100 parts water
 - For heavy cleaning, 2–3 parts Synteko REMOVER to 100 parts water
- Soak a cloth in the mixture; do not pour it directly onto the floor.
- Wet mop, let the mixture act for a few minutes and then dry mop.
- 5. Further cleaning with 1 part vinegar to 9 parts water is recommended if sanding and recoating is to be done.
- The floor must be completely dry before screening and recoating.

HOW DO I USE RE-COVER 1620?

- 1. Clean the floor with a Synteko REMOVERr solution.
- Make sure the floor is completely dry before applying Synteko RE-COVER.
- 3. Apply it thinly with a rubber spatula, floor cloth or similar.
- 4. Allow the floor to absorb the RE-COVER for 10–15 minutes before applying it again (if necessary).
- Let the surface dry for 20 minutes and polish the floor with a clean, dry, non-flocculent floor cloth.
- 6. The floor may be used after 2–4 hours.
- 7. Read also separate product information for RE-COVER 1620.

HEALTH & SAFETY INFORMATION

FOR PROFESSIONAL USE ONLY! Detailed information and guidance is provided in our MSDS (Material Safety Data Sheet) www.synteko.com. The following only represents a selection of important information.

RISK OF SELFIGNITION! CONTAINS DRYING OIL. COLLECT AND KEEP SPILLAGES, USED RAGS ETC IN FIREPROOF CONTAINER AND DESTRUCT.

Keep out of reach of children. If medical advice is needed, have product container or label at hand. Do not get in eyes, on skin, or on clothing. Call a POISON CENTER or doctor/physician if you feel unwell. Dispose of contents and container in accordance with all local, regional, national or international regulations. Contains: neodecanoic acid, cobalt salt. May produce an allergic reaction. EU limits for this product (cat. A/i): 500 g/l (2010). This product contains max 8 g/l VOC.

Our information is based on laboratory tests and is considered a guide in connection with choice of product and working method. As your working conditions are beyond our control, we do not assume any responsibility for the results. Our responsibility covers exclusively personal injury and damage to property, which actually have been proved subsequent to faults and defects inone of the products manufactured by us.

Producer: Sika Estonia OÜ, Estonia www.synteko.com